







LIFE'S COMING TOGETHER.



#### **CONSTRUCTION SCHEDULE MACRO SCHEDULE**







Dates: Color code

\* The construction on evolving process. The construction on evolving process. The construction of the const

<sup>\*</sup> The construction progress schedule presented in this report is subject to change based on evolving project conditions and unforeseen factors.

### SPECIFICATION UPGRADES \_\_\_\_\_



**Flooring and Dado** 

All Bedrooms Engineered Wooden Flooring

All Bathrooms

Flooring in Imported Marble, Dado in Premium

Vitrified

Powder Rooms Flooring in Imported Marble, Dado in Premium

Vitrified

Plumbing and Bathroom Fixtures

Bathroom Counter Imported Marble for the Counters

Kitchen Counter and

Sink

Quartz Counter (uninstalled)

**False Ceiling** 

Apartment Gypsum False ceiling with LED concealed lighting

as per default design

Toilet Modular False Ceiling with Calcium Silicate Board

Tiles or Equivalent

Power Supply; Electrical and

**Communication Systems** 

Wiring Concealed FRLS Wiring in PVC conduits

Earth Leakage Circuit Breaker (ELCB) and Miniature

Circuit Breakers (MCB)

**Doors and Windows** 

Main Door 8' Solid Core Double Leaf Doors with Designer Veneer

Internal Doors 7' Solid Core Veneered Flush Doors

Bathroom Doors 7' Solid Core Flush Doors with Veneer & laminate

**Utilities & Services** 

Solar Water Heater Provided as per M.O.E.F Norms (for Specific


Apartments)

Elevators Schindler or Equivalent


<sup>\*</sup> Specifications have been upgraded vis-à-vis the specifications declared on the RERA application / website.

## KEY PLAN 2 DIMENSIONAL \_\_\_\_\_















## PROJECT PROGRASS STATUS \_\_\_\_\_

COMPLETED







77 Life\_FY 24-25\_Q3\_Report 11

**IN PROGRESS** 

## PROJECT PROGRASS COMMON AREA








## PROJECT PROGRASS COMMON AREA



#### **Basement:**

**Services w**orks in progress (70% Completed)





#### Arrival Area:

Flooring works in progress (10% Completed)

































14<sup>th</sup> Level External Plastering works in progress



#### Atrium external plastering works in progress



# **PROJECT ARTIST IMPRESSION**

OF AMINITIES \_\_\_\_\_

























New Goals, Learnings, and Beginnings!



# Thank you

Do reach out to us in case you need any further information and / or clarification.

We are happy to be of service!





